



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) Oil Spill

3. Incident Details

- i. Date of Incident: 17TH MAY, 2015 ii. Date first reported:
iii. Date of first investigation: 18TH MAY, 2015
iv. Date of follow-up investigation:
v. Time investigation started: 12:55 HRS
vi. Estimated quantity spilled: 0.110 BBLs

4. Site Details

- i. Site/Location: 4" EBOCHA IT FLOWLINE ALONG OLD EBOCHA FERRY ROAD, OBRIKOM Community
ii. Position of Spill/Leak: N 05° 26' 50" S E 006° 40' 33" .8

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock 11 O'Clock ✓

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

1. Lion (A)

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects ☒ Others (Specify) all of them

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify) ALA

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

(a) Community *(Indicate name)*

i.

ii.

iii.

iv.

(b) Land *(Indicate area in m²)*

i.

ii.

iii.

iv.

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation..... NAOC SHOULD IMPROVE
ON THEIR SURVEILLANCE TEAM

12. Time Investigation ended..... 13:30 HRS