

Note: This JIV form is to be completed and signed by all participating parties in the field

2. Type of Complaint/Incident:

- ### 3. Incident Details

- #### 4. Site Details

- ### iii. Spill area

- #### iv. Structural Controls in Place

- ### 5. Circumstances Around Spill Point

- ### i. Visual observation of Hole Position

- ### ii. Type of Oil Contaminant

- ### iii. Facility

- #### iv. Cause of Spill

- #### v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify) N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. KPONKPONKIRI

ii. _____

iii. _____

iv. _____

(b) Land (Indicate area in m²)

i. N/A

ii. _____

iii. _____

iv. _____

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

NAOC SHOULD PUT MORE EFFORT INTO PIPELINE SECURITY

12. Time investigation ended..... 13:20 HRS