

2024/SAR/101



## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

### JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED (NAOC)

#### 2. Type of Complaint/Incident:

- ☒ Oil Pollution      ☒ Fire/Explosion      ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

#### 3. Incident Details

- i. Date of Incident: 12/05/2024      ii. Date first reported: 12/05/2024  
iii. Date of first investigation: 12/05/2024  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 14:10 HRS  
vi. Estimated quantity spilled: 1 BBL

#### 4. Site Details

- i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT OYEREGBENE  
ii. Position of Spill/Leak: N 04° 30' 05.1" E 086° 03' 52.1"

##### iii. Spill area

- ☒ Land      ☒ Swamp      ☒ Freshwater      ☒ Mangrove      ☒ Coastline  
☒ Near shore      ☒ Offshore      ☒ Others (Specify) .....

##### iv. Structural Controls in Place

- ☒ Boom      ☒ Trenches      ☒ Bund Wall      ☒ Sorbents      ☒ Others (Specify) NIL

#### 5. Circumstances Around Spill Point

##### i. Visual observation of Hole Position

- ☒ 12 O'Clock      ☒ 10 O'Clock      ☒ 2 O'Clock      ☒ 3 O'Clock  
☒ 4 O'Clock      ☒ 5 O'Clock      ☒ 6 O'Clock

##### ii. Type of Oil Contaminant

- ☒ Crude Oil      ☒ Condensate      ☒ Chemicals      ☒ Refined Products  
☒ Others (Specify) .....

##### iii. Facility

- ☒ Pipeline      ☒ Flow Line      ☒ Wellhead      ☒ Manifold      ☐ Flow Station      ☐ Rig  
☒ Storage Tank      ☒ Compressor Plant  
☒ Others (Specify) .....

##### iv. Cause of Spill

- ☒ Corrosion      ☒ Equipment Failure      ☒ Third Party Interference      ☒ Accident  
☒ Operational Error      ☒ Others (Specify) .....

##### v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks      ☒ Drilled Holes      ☒ Blasting      ☒ Theft      ☒ Acid  
☒ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (Specify) ... NIL

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others (Specify) ... NIL

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. OVEREGBENE

ii. ....

iii. ....

iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

i. 99.99M<sup>2</sup>

ii. ....

iii. ....

iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

9. Samples taken... *N/A* .....

10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation.....

*NAOC SHOULD PUT MORE EFFORT INTO PIPELINE SECURITY*

12. Time investigation ended... *15:17RS* .....