



Note: This JIV form is to be completed and signed by all participating parties in the field

2. Type of Complaint/Incident:

- ### 3. Incident Details

- #### 4. Site Details

- ### iii. Spill area

- #### iv. Structural Controls in Place

- ## 5. Circumstances Around Spill Point

- ### i. Visual observation of Hole Position

- ### ii. Type of Oil Contaminant

- ### iii. Facility

- #### iv. Cause of Spill

- #### v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify) N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. Lagos State

ii. _____

iii. _____

iv. _____

(b) Land (Indicate area in m²)

i. N/A

ii. _____

iii. _____

iv. _____

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☒ Video coverage ☒ Mapping

9. **Samples taken**..... *N/A*

10. **Investigation carried out by**

☒ Foot ☒ Boat ☒ Aircraft

11. **Remarks/Recommendation**.....

NADOC SHOULD PUT MORE EFFORT INTO PIPELINE SECURITY.

12. **Time investigation ended**..... *15:30 HRS*