



2024/SAR/077

## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

### JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: Nigeria Agip Oil Company

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify) .....

3. Incident Details

i. Date of Incident: 17/04/2024 ii. Date first reported: 17/04/2024

iii. Date of first investigation: 17/04/2024

iv. Date of follow-up investigation: .....

v. Time investigation started: 12:46 HRS

vi. Estimated quantity spilled: ± 0.20 BBL

4. Site Details

i. Site/Location: 6" OGBONBIRI/TERIDABA PIPELINE AT OKPOTUWARI

ii. Position of Spill/Leak: .....

iii. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (Specify) .....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock

☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock

ii. Type of Oil Contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☐ Others (Specify) .....

iii. Facility

☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland    ☒ Fish Pond    ☒ Vegetation    ☒ Fishing Net    ☒ Surface water  
☒ Movable Objects    ☒ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation    ☒ Oil stained fishing nets    ☒ Dead floating fishes  
 Dead floating crabs    Withering of vegetation    Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW    ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. .....  
 ii. .....  
 iii. .....  
 iv. .....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. .....  
 ii. .....  
 iii. .....  
 iv. .....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | N/A                |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | N/A                |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | N/A                |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      | N/A                |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

9. Samples taken .....

10. Investigation carried out by ..

☒ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation. JIV WAS SUCCESSFULLY COMPLETED REPAIR  
WAS CARRY-OUT SAME DAY

12. Time Investigation ended .....