



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: 09/05/23 ii. Date first reported: 09/05/2023

iii. Date of first investigation: 09/05/23 iv. Spill Incident No: 2023/SAR/NL/063

v. Date of follow-up investigation:

vi. Time investigation started: 14:26

vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL

4. Site Details

i. Site/Location: 14" OGBOINBIRI/TEBIDABA PIPELINE AT OKBOTUNNA

ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW

iv. Spill Co-Ordinates: N(m) 04° 44' 53.1"
E(m) 005° 58' 37.8"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☒ Frenchies ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify)

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Jacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify)..... N/A

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.... N/A

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others N/A

8. Extent of Impact

a) Community (indicate name)

i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☒ Tidal

☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation.....

OPERATOR (AGPP) SHOULD IMPROVE
ON THEIR SURVEILLANCE.....

13. Time investigation ended.....

16:54 HR