

2024/LA/HGLI/023



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: INDORAMA GLENE PETROCHEMICAL LIMITED

2. Type of Complaint/Incident:

- ☐ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) GAS LEAK

3. Incident Details

- i. Date of Incident: 30-5-2024    ii. Date first reported: 30-05-2024  
iii. Date of first investigation: 31-05-2024  
iv. Date of follow-up investigation: \_\_\_\_\_  
v. Time investigation started: 13:29 HRS  
vi. Estimated quantity spilled: GAS LEAK

4. Site Details

- i. Site/Location: 8° 08' 03" - INDORAMA NGH PIPELINE AT OMH-  
EVA - UBIMA COMMUNITY, ILEWERE LGA  
ii. Position of Spill/Leak: NOS 06 068° 2006 53' 09.5"

iii. Spill area

- ☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (Specify) \_\_\_\_\_

iv. Structural Controls in Place

- ☐ Boom    ☐ Trenches    ☐ Bund Wall    ☐ Sorbents    ☐ Others (Specify) \_\_\_\_\_

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock    ☐ 10 O'Clock    ☐ 2 O'Clock    ☐ 3 O'Clock  
☐ 4 O'Clock    ☐ 5 O'Clock    ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (Specify) GAS LEAK

iii. Facility

- ☒ Pipeline    ☐ Flow Line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant  
☐ Others (Specify) \_\_\_\_\_

iv. Cause of Spill

- ☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☒ Theft    ☐ Acid

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (Specify) .... *fish* .....

### ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
Dead floating crabs Withering of vegetation Others (Specify) *fish*

### iii. Delineation of Impacted area

*CASLE* ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. .... i. ....  
ii. .... ii. ....  
iii. .... iii. ....  
iv. .... iv. ....

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken. NK SAMPLES COLLECTED AT THE TIME OF JI

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation. Repair was carried out on the  
pipeline immediately after JI exercise. Surveillance  
showed by intensity on the pipeline right of way

12. Time Investigation ended. 15:16 hrs