

Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

Samples taken... NIL

Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

1. Remarks/Recommendation... SPDC should properly check their
clamps before fixing to prevent future occurrences.

12. Time Investigation ended... 1733HRS

13. Name and Signature of Participants