

1/2015/LAR/100/282

167



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) CRUDE OIL

3. Incident Details

- i. Date of Incident: 28/06/2015 ii. Date first reported: 29/06/2015
iii. Date of first investigation: 03/07/2015
iv. Date of follow-up investigation: _____
v. Time investigation started: 14:10 HRS
vi. Estimated quantity spilled: 17.37/64LS (BURNT OFF), 15 BBLs WITHIN DRAINAGE

4. Site Details

- i. Site/Location: EBOCHA CRUDE OIL STOCK TANK # AND 2 EBOCHA OIL CENTRE, OKWUZI, ONEKGA LGA
ii. Position of Spill/Leak: N05° 27' 34.4" E006° 41' 48.9"
iii. Spill area: N05° 27' 37.0" E006° 41' 50.0"
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☒ Near shore ☐ Offshore ☐ Others (Specify) _____
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) _____

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☒ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) _____

iii. Facility

- ☐ Pipeline ☐ Flow Line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☒ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) TANK EXPLOSION EXTERNAL ATTACK

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) _____

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify) **Soots Deposit on vegetation & roofs of houses**

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation. NAOC SHOULD PROVIDE IMMEDIATE PALLIATIVE MEASURES
TO AFFECTED COMMUNITIES, RAPID ASSESSMENT OF IMPACTED ENVIRONMENT
CLEAN-UP OF THE IMPACTED AREA & REPAIR OF AFFECTED AREA IN THE FACILITY
REPAIRS TO BE CARRIED OUT

12. Time Investigation ended