



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY [NAOC]

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 20/07/2015 ii. Date first reported: 20/07/2015
iii. Date of first investigation: 23/07/2015
iv. Date of follow-up investigation:
v. Time investigation started: 4pm
vi. Estimated quantity spilled: 1894 BBLs

4. Site Details

- i. Site/Location: 2.4" OGODA - BRASS PIPELINE AT EMAGD-KURBO
ii. Position of Spill/Leak: N 04° 42' 28.3" E 006° 25' 28.2"
iii. Spill area
☒ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☒ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☒ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

i. EMAGD-KUGBO

i. 7527995.51 m²

ii.

ii.

iii.

iii.

iv.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>
<u> // </u>	<u> // </u>	<u> // </u>	<u> // </u>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. *NAOC Should Clean-up the impacted site immediately and intensify surveillance on its facility to avoid future occurrence*

12. Time Investigation ended.....