

1470530



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 25th August 15 ii. Date first reported:
iii. Date of first investigation: 27th August 2015
iv. Date of follow-up investigation: 28th August 2015
v. Time investigation started: 08:35 hrs
vi. Estimated quantity spilled: 64 bbls

4. Site Details

- i. Site/Location: 28° Bonny-Bonny M/L @ Ayaminin
ii. Position of Spill/Leak: N04° 26' 58.2" E007° 10' 38.4"

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0' Clock ☐ 10 0' Clock ☐ 2 0' Clock ☐ 3 0' Clock
☐ 4 0' Clock ☐ 5 0' Clock ☐ 6 0' Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water

☐ Venerable Objects

☐ Others (Specify)

Raffia Palm / mangrove

ii. Nature of impact

☒ Oil stained vegetation

☐ Oil stained fishing nets

☐ Dead floating fishes

☐ Dead floating crabs

☐ Withering of vegetation

☐ Others (Specify)

mangrove

iii. Delineation of Impacted area

☒ Within Company's facility/ROW

☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

i. i.

ii. ii.

iii. iii.

iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation

The spill point was clamped.
SPDC should clean - the impacted site and
also increased surveillance on their facility

12. Time Investigation ended

3:15 hrs