

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY (SPDC)

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 10/03/2025 ii. Date first reported: 10/03/2025
iii. Date of first investigation: 17/03/2025
iv. Date of follow-up investigation:
v. Time investigation started: 9:05am
vi. Estimated quantity spilled: 7 bbls

4. Site Details

- i. Site/Location: 4" OPUKUSHI WELL 241 F/L @ AGBIDIAMA
ii. Position of Spill/Leak: N4 918275 E5 748840

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0' Clock ☒ 10 0' Clock ☒ 2 0' Clock ☒ 3 0' Clock
☒ 4 0' Clock ☒ 5 0' Clock ☒ 6 0' Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☐ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the Incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of Impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 Dead floating crabs
 Withering of vegetation
 Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii. Agbidiara
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii. 0.043 HA
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>X</u>	<u>A</u>	

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>X</u>	<u>A</u>	

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>X</u>	<u>A</u>	

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>X</u>	<u>A</u>	

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

TIV was conclusive
Urgent Clean-up is needed.

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA

1. GODFREY ENEMIFA  17/03/2025

2.

3.

❖ NUPRC/NMDPRA

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. Engr. DREY ARIEGHA  17/03/2025

2.

3.

❖ LOCAL GOVERNMENT COUNCIL


1.

2.

3.


❖ COMPANY

1. SIBOKI, AKPOANANOR 17/03/25

2. OMUTA ISRAEL  17/3/2025

3.

❖ COMMUNITY

1. Chike P-ogbere  17-03-2025

2. Freeman Matthew  17-03-2025

3.