



2025/SAR/045

284

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: OMDO ENERGY RESOURCES NIGERIA LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 25/04/2025    ii. Date first reported: 25/04/2025  
iii. Date of first investigation: 25/04/2025  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 1108HRS  
vi. Estimated quantity spilled: 0.31 BBL

4. Site Details

- i. Site/Location: 24" OGODA/BRASS PIPELINE AT AKIPILAY  
ii. Position of Spill/Leak: N04° 35' 19.1" E 006° 23' 07.6"

iii. Spill area

- ☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom    ☒ Trenches    ☒ Bund Wall    ☒ Sorbents    ☒ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock    ☒ 10 0'Clock    ☒ 2 0'Clock    ☒ 3 0'Clock  
☒ 4 0'Clock    ☒ 5 0'Clock    ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (Specify) .....

iii. Facility

- ☒ Pipeline    ☒ Flow Line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (Specify) .....

## 6. Impact of Incident

## i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (Specify) .....

## ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others (Specify) .....

## iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

i. AKIPILAI

(b) Land (Indicate area in  $m^2$ )i. 17.01  $m^2$ 

ii. ....

ii. ....

iii. ....

iii. ....

iv. ....

iv. ....

(c) Creek/Creek lets

☐ Tidal☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| N/A  |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☐ Tidal☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| N/A  |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☐ Tidal☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| N/A  |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☐ Tidal☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| N/A  |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

## 8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

## 9. Samples taken.....

## 10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

## 11. Remarks/Recommendation.....

OANDO ENERGY RESOURCES NIGERIA  
LIMITED SHOULD MOB UP THE IMPACTED  
AREA

## 12. Time Investigation ended.....

## 13. Name and Signature of Participants

## ❖ NOSDRA

1. DERIGHA EVEREST O.

2. ....

3. ....

*[Signature]* 25/04/25

## ❖ NUPRC/NMDPRA

1. ....

2. ....

3. ....

## ❖ STATE MINISTRY OF ENVIRONMENT

1. ANULA HAPPINESS

2. ....

3. ....

*[Signature]* 25/05/2025

## ❖ LOCAL GOVERNMENT COUNCIL

1. ....

2. ....

3. ....

## ❖ COMPANY

1. AKI JOE OANDO CRM *[Signature]*

2. OMONSO MIKE OANDO EHSQ *[Signature]* 25/4/2025

3. ....

## ❖ COMMUNITY

1. ....

2. ....

3. ....