

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation... DELIMITATION OF IMPACTED AREA CARRIED OUT
AWAK IV, CRV TEAM TO CARRY OUT REPAIR, IMMEDIATE
CLEAN-UP OF IMPACTED AREA REQUIRED

12. Time Investigation ended... 18:07 HRS.....

13. Name and Signature of Participants