

CLEAN-UP/REMEDIATION SITE CLOSE-OUT FORM

1. Site Details

- i. Company: HEIRS ENERGIES LIMITED
- ii. Asset/Facility: 6" OBIGBO - KOMKOM MANIFOLD DELIVERY LINE
- iii. Location: KOM-KOM
- iv. Incident No: IN-0678 Date of incident: 27/11/2025
- v. Date of JIV: 28/11/2025
- vi. Estimated quantity spilled (bbls): 6 bbls
- vii. Estimated quantity recovered (bbls): 4.4 bbls
- viii. Impacted area (m²): 3,240 m² Depth of impact (m):

2. Site characterization

- i. Contaminated media: ☒ Vegetation ☒ Soil ☐ Others.....
- ii. Type of soil: Loamy
- Land use: ☐ Agriculture ☐ Industrial ☐ Residential ☐ Commercial
- ☐ Reserved Area ☐ Others.....

3. Clean - up/Remediation Details

- i. Clean-up/Remediation Work Plan Approved? ☒ Yes ☐ No
- ii. Approved method(s): Cutting and removal of impacted vegetation
- iii. HSE plan Approved? ☒ Yes ☐ No
- iv. Additives/chemicals applied. NO
- a. N/A
- b. N/A
- c. N/A
- v. Date clean-up/Remediation commenced: 19/01/2026
- vi. Date clean-up/Remediation ended: 02/02/2026



4. Waste Management (Waste Vendor): OYA waste management LTD.

i. Types of waste generated

a. Vegetations

b.

c.

ii. Total mass of waste generated (kg) 34,345.35 kg

iii. Method of disposal: ☐ Recycling ☐ Land farming

☐ Land filling ☒ Control Burning/Incineration ☐ Others

5. Other comments: Clean-up of the oil spill site at Kom-Kom Community in Obigbo was properly carried out.

6. Participants:

a. Company

i. OZONDA PRINCESS - C. Okeke 02/02/2026

ii.

b. NOSDRA

i. ENGR. GODSPower ISHEKE

ii.

c. NUPRC

i.

ii.

d. State Ministry of Environment

i. Dr. Moses O. Bereiweris ~~30/01/26~~

ii.

e. Community

i. Frank Anyesor Gbure 02/02/26

ii.

f. Contractor(s)

i. Sharon Ogedegbe-George 2/2/26 CAWA Eng-Consult

ii.

g. Other Agencies

i.