

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (N.AOC)

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 7/10/15 ii. Date first reported: 7/10/15
iii. Date of first investigation: 7/10/15
iv. Date of follow-up investigation:
v. Time investigation started: 14:21 HRS
vi. Estimated quantity spilled: 0.10 BARRELS

4. Site Details

- i. Site/Location: 18" TERBIDABA BRASS PIPELINE @ MBIKIBA, BAYELSA
ii. Position of Spill/Leak: N 04° 28' 54.4" E 006, 05' 58.5"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0° Clock ☒ 10 0° Clock ☒ 2 0° Clock ☒ 3 0° Clock
☒ 4 0° Clock ☒ 5 0° Clock ☒ 6 0° Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects ☒ Others (Specify)

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes

☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify)

iii. Delineation of Impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
ii.
iii.
iv.

(b) Land (Indicate area in m²)

- i.
ii.
iii.
iv.

(c) Creek/Creek lets

☒ Tidal ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation..... Improve Surveillance on Facility.
Jiv was Termed Conclusive.