



# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NAOC
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details  
i. Date of Incident: 11/11/2015    ii. Date first reported: 19/11/2015  
iii. Date of first investigation: 19/11/2015    iv. Spill Incidence No.: .....  
v. Date of follow-up investigation: .....  
vi. Time investigation started: 10:25 HRS.  
vii. Estimated quantity spilled(bbls): 8 Bbls.    viii. Quantity Recovered: 0.377 Bbls.
4. Site Details  
i. Site/Location: 10' clough creek / Tub. Plat Apa  
ii. State: Bayelsa    iii. L.G.A.: Sulcat  
iv. Spill Co-ordinates: N(m) 04° 43' 43.8"  
E(m) 005° 51' 15.9"  
v. Spill area  
☐ Land    ☒ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....  
vi. Structural Controls in Place  
☐ Boom    ☐ Trenches    ☐ Bund wall    ☐ Sorbents    ☒ Others (specify) nil
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☐ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☐ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (specify).....  
iii. Facility  
☒ Pipeline    ☐ Flow line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify).....  
iv. Cause Of Spill.  
☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify).....  
v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (specify).....



1. **Properties impacted by the incident**

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (specify).....

ii. **Nature of impact**

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. **Delineation of impacted area**

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift  
☐ Permanent ☒ Others *Vegetation*

8. **Extent of Impact**

a) **Community** (indicate name)

- i. *APOI*  
 ii. ....  
 iii. ....  
 iv. ....

b) **Land** (indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

b) **Creeks/Creek lets**

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

c) **Swamp**

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

d) **River**

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

e) **Shoreline/water**

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken *NA*

11. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation *NAOC should be requested to clean up impacted areas.*

13. Time investigation ended *14:45 hrs.*