



NATONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NAOC
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)
3. Incident Details
 - i. Date of Incident: 27/7/13 ii. Date first reported: 28/7/13
 - iii. Date of first investigation: 28/7/13
 - iv. Date of follow-up investigation:
 - v. Time investigation started: 11:23am
 - vi. Estimated quantity spilled: NIL
4. Site Details
 - i. Site/Location: OBIAFU 38T well head omoku, onelga. R/S
 - ii. Position of Spill/Leak: N05°26'26.3" E006°36'43.7"
 - iii. Spill area
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify) NIL
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) NIL
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock NIL
 - ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) NIL
 - iii. Facility
☐ Pipeline ☐ Flow line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
 - v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify)

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... **NIL**

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. **OBIAFU**
 ii.
 iii.
 iv.

b) Land* (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☒ Foot ☐ Boat ☐ Aircraft

11. **Remarks/Recommendation**..... Constant Surveillance should
be deployed to reduce the number of
such incidents. Such as Theft.

12. **Time investigation ended**.....