

2016/LAR/023/072

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 10/03/16 ii. Date first reported:
iii. Date of first investigation: 11/03/16
iv. Date of follow-up investigation:
v. Time investigation started: 13.15 hrs
vi. Estimated quantity spilled: oil

4. Site Details

- i. Site/Location: 6" Taylor Geel 2S F/L @ AKARATOLU
ii. Position of Spill/Leak: N 05° 06' 01.1" E 006° 30' 05.5"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) Seasonal Swamp

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0° Clock ☐ 10 0° Clock ☒ 2 0° Clock ☐ 3 0° Clock
☐ 4 0° Clock ☐ 5 0° Clock ☐ 6 0° Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) 2" valve installed @ 2 o'clock

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *N/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i. *N/A*
 ii.
 iii.
 iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: diagonal line]</i>			
	<i>[Handwritten: diagonal line]</i>		
			<i>[Handwritten: diagonal line]</i>
			<i>[Handwritten: diagonal line]</i>

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: diagonal line]</i>			
	<i>[Handwritten: diagonal line]</i>		
			<i>[Handwritten: diagonal line]</i>
			<i>[Handwritten: diagonal line]</i>

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: diagonal line]</i>			
	<i>[Handwritten: diagonal line]</i>		
			<i>[Handwritten: diagonal line]</i>
			<i>[Handwritten: diagonal line]</i>

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten: diagonal line]</i>			
	<i>[Handwritten: diagonal line]</i>		
			<i>[Handwritten: diagonal line]</i>
			<i>[Handwritten: diagonal line]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

*N/AOC should increase surveillance
and density. Repair was effected on the
Flowline*

12. Time Investigation ended

15:15 hrs