

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NACC
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 21/11/15 ii. Date first reported: 21/11/15
 - iii. Date of first investigation: 21/11/15 iv. Spill Incidence No.:
 - v. Date of follow-up investigation:
 - vi. Time investigation started: 12:59 HRS
 - vii. Estimated quantity spilled(bbls): 16 bbls viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 10' CLOUGH CREEK/TEB. PLAT APOI.
 - ii. State: BATLSA iii. L.G.A.: SILGA
 - iv. Spill Co-ordinates: N(m) 04° 43' 47.2"
E(m) 008° 51' 12.2"
 - v. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - vi. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) NIL
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. Cause Of Spill.
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify).....



1. **Properties impacted by the incident**

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. **Nature of impact**

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. **Delineation of impacted area**

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. **Extent of Impact**

a) **Community** (indicate name)

- i. APOT
 ii.
 iii.
 iv.

b) **Land** (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) **Creeks/Creek lets**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... NA

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation.....

NAOC should be requested to strengthen the security network on their facilities.

13. Time investigation ended

14. N