



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC INCIDENT NO: 2016/NL/LAR/007/013

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 03-04-2016 ii. Date first reported: 04-04-2016
iii. Date of first investigation: 11-04-2016
iv. Date of follow-up investigation:
v. Time investigation started: 14.30 HOURS
vi. Estimated quantity spilled: NIL (AREA SET ON FIRE)

4. Site Details

- i. Site/Location: MGBEDE 8SS WELL HEAD @
MGBEDE COMMUNITY.
ii. Position of Spill/Leak: N 05° 27' 23.3"
E 006° 41' 31.2"
iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point:

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☐ Theft ☒ Acid
☒ Others (Specify) WELL HEAD SET ON FIRE

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
ii.
iii.
iv.

(b) Land (Indicate area in m²)

- i.
ii.
iii.
iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken. YES

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation

1. Repair the Facility.
2. Increase Surveillance.

12. Time Investigation ended

13. Name and Signature of Participants

❖ NOSDRA

1. KOM S ABAM [Signature] 11/04/2016
2. _____
3. _____

❖ DPR

1. _____
2. _____
3. _____

❖ STATE MINISTRY OF ENVIRONMENT

1. ORDN JAMES [Signature] 11/04/16 (RSMGRV)
2. _____
3. _____

❖ LOCAL GOVERNMENT COUNCIL

1. _____
2. _____
3. _____

❖ COMPANY

1. Johnson Lucky NASE HSE [Signature] 11/04/16
2. GEORGEWILL BIBO NASE NICE [Signature] 11/04/16
3. M. HADEKE OTTOM NASE PRO [Signature] 11/04/16

❖ COMMUNITY

1. OWUMADI JOSEPH [Signature] 11/04/16
2. _____
3. _____