



NAOC

FIELD/SITE INSPECTION REPORT

LOCATION: 10" Oshie – Ogodu pipeline at Idu Ekpeye

PURPOSE OF VISIT: To carry out JIV to the burnt area on the awarded clean up site to Franco Int.

DATE/TIME OF INSPECTION: 14/05/14 @ 12 noon.

OBSERVATIONS: Section of the site engulfed in fire also observed as reported by NAOC monitoring team during their visit on 6-3-2014.
(i) The burnt sections of the site were also delineated during the JIV inspection.
(ii) The cause of the incident yet to be ascertained as at the time of the inspection.

REMARKS/RECOMMENDATIONS: Surveillance and fire break should be enhanced to forestall and prevent the reoccurrence of fire outbreak.