





Path: G:\30\_Project\Nigeria\Renaissance\Geomatics\2026\OIL\_SPILL\_PROJECTS\000433\Oil Spill\Maps\EP2026030000000163.aprx



- Legend
- Incident Points
  - Roads - Major
  - Oil Pipeline
  - 3rd Party Heavy Impact (Land/Swamp)
  - Renaissance Heavy Impact (Land/Swamp)
  - Oil Spill Impacted Area
  - ROW Parcels

IMPACTED AREA: 1.005239 Ha

MAP BASED ON DATA ACQUIRED DURING FIELD WORK


INCIDENT DATE: 26/02/2026  
INVESTIGATION DATE: 28/02/, 03 & 08/03/2026  
INCIDENT CAUSE: SABOTAGE  
VEGETATION TYPE: THICK BUSH  
TERRAIN TYPE: SEASONAL SWAMPY AREA

MAP DISCLAIMER

Data sourced from outside Renaissance is sometimes used. Therefore, Renaissance cannot accept liability for any errors, omissions, or positional accuracy on usage of this map. Users are strongly cautioned to verify all information before making any decisions. Users should promptly inform the appropriate Renaissance GEOMATICS Team of any error for review and necessary update.

Horizontal Coordinate Reference System  
Name: GCS WGS 1984  
Datum: WGS 1984  
Map Units: Degree

Vertical Coordinate Reference System  
Datum: MSL  
Elevation/Depth: Elevation  
Map Units: Degree



Scale: 1:1,250



JIV MAP OF AREAS AFFECTED BY CRUDE OIL  
SPILLAGE ALONG 16" EGBEMA TO ASSA  
PIPELINE AT ETEKWURU

Incident ID-000433

|                                    |                                |
|------------------------------------|--------------------------------|
| Author: Frimenjibo, Lucky          | Data Captured By: Deborah Udoh |
| Approved By: Renaissance Geomatics | Date: 13/03/2026               |
| Drawing No.: EP2026030000000163    | Originator: Saniyo Eworitse    |
| Report No.:                        | Revision:                      |

RESTRICTED