



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unlimited	
Reporting Officer		Okechukwu Udeji	
Designation		General Manager, Offshore Operations	
Phone Number		+234 817 206 7597	
Email Address		OUdeji@seplatenergy.com	
Incident Number		005 / 2026	
Section 2 - Location			
State / LGA		Ubit PP / Around Eku-EB / OML67 / 4° 15.6"N / 8° 04.1"E	
Coordinates of spill		4° 15.6"N / 8° 04.1"E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others:	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		4/27/2026 Time: 12:30 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☒ Others: Well head Platform	
Cause of spill		Equipment failure – Platform shut down on Test Separator level switch (LSH). Wells were also found shut in and Separator inlet SDV shut while the export line SDV was found in open position. This is suspected to have caused back filling of the Test Separator, leading to liquid carryover to the instrumentation and release to the sea.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent X Others: 1) 1) Platform instrumentation system was isolated and drained, and the leak stopped. 2) Mechanical agitation was conducted to disperse the sheen.	
Product Data	☒ Persistent		☐ Non-Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.028302bbl of crude oil based on sheen appearance	
	Coverage	About 900m x 50m of 100% silvery sheen on the sea.	
	Direction of travel	South West	
Section 5 - Weather			
METEOROLOGICAL DATA		NIMET weather forecast	
Wind Direction (wind direction given from)	South West		
Initial Wind Speed	8knots		
Air Temperature (C or OF)	NA		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐ Ebb ☐		
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☒	
Recovery of free phase oil	Yes ☐	No ☒	
Booming	Yes ☐	No ☒	
Wild life rehabilitation	Yes ☐	No ☒	
Dispersant application	Yes ☐	No ☒	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)
Precautionary measures taken since the spillage/leakage occurred to prevent hazard hazards that may arise: 1) Platform instrumentation system was isolated and drained, and the leak stopped. 2) Mechanical agitation was conducted to disperse the sheen.

Section 8– Equipment	
On Site	

REPORTING OFFICER: For: **Okechukwu Udeji** Iyiola Olumide
DESIGNATION: **General Manager, Offshore Operations**

Initial
NA

Signed by:
Iyiola Olumide

SIGNATURE:

28-Apr-26 | 17:56 WAT
DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*