



National Oil Spill Detection and Response Agency

FORM B

RISK BASED ASSESSMENT OF OIL SPILL INCIDENCE (RBA)

Note: This report must be submitted within 2 weeks of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name	Seplat Energy Producing Nigeria Unlimited		
Reporting Officer	Iyiola Olumide		
Phone Number	08102820349		
Email Address	IOlumide@seplatenergy.com		
Incident Number	006 / 2026		
Incident Date	4/28/2026		
Spill Stopped Date	4/28/2026		
Section 2 – Location			
Facility Address	BRT Diesel Tank Area / 4° 24'32"N / 7° 08'36"E		
State/ LGA	Rivers State		
Location OML:	GPS Coordinate	4° 24'32"N / 7° 08'36"E	
Section 3 – Spill Details			
Date and Time of site assessment	4/28/2026 Time: 14:30 hours local time		
Cause of spill	Company	Third Party Interference	Others
	☐ Corrosion ☐ Equipment Failure: ☐ Operational/ Maintenance Error ☐ Bund wall overflow	☐ Vandalization ☐ Oil Theft ☐ Illegal Refining ☒ Others: During a diesel inter-tank transfer operation using flexible hose, the discharge hose slipped off its fastener at the receiving tank, resulting in a release of diesel (AGO) into the concreted bund wall and a small area of the ground just outside the bund wall.	☐ Accident ☐ Mystery Sheen
Estimated Quantity Spilled (bbl)	About 0.1bbl of discharged AGO (Diesel) made contact with ground surface		
Estimated Quantity Recovered	Nil		
Control Measures	☐ Clamping ☐ Well Shut-in ☐ Valve Shut-in ☐ Flow Station Shut Down ☒ Others (specify): The AGO pumping operation was immediately halted by the attendant, preventing further release.		
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tankers ☐ Tank Trucks ☐ Barge ☐ Tanker Vessel Pipeline		

		PIPELINE (Specify pipeline diameter.....) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Delivery line ☐ Export Line ☐ Gas Line ☐ Others:
		STORAGE TANKS ☐ Underground Storage Tank ☐ Above-Ground Storage Tanks ☒ Others (specify): BRT Diesel Tank Area
		PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow Station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Others (specify).....
Section 4 – Basic Types of Oil		
Very Light Oil	☐ Jet oil or Gasoline	
Light Oil	☐ Diesel ☐ No. 2 fuel oil ☐ Light Crude	
Medium Oil		
Heavy Oil	☐ Heavy crude oil ☐ Bunker C ☐ No.6 Fuel oil	
Section 5 – Site Characterization		
Land Use	Not Applicable	
Topography	☐ Sand beach ☐ Dock ☐ Shoreline ☐ Swamp ☐ Others (specify).....	
Surficial Geology	Soil Type ☐ Sandy ☐ Clay ☐ Silt ☐ Loam ☐ Peat	
	Soil Texture ☐ Very Fine ☐ Fine ☐ Medium ☐ Coarse ☐ Very Coarse	
	Soil Structure ☐ Granular ☐ Blocky ☐ Prismatic	
	Soil Permeability	
	☐ Slow ☐ Moderate ☐ Rapid	☐ Permeable ☐ Semi Permeable ☐ Impermeable
	☐ Potential preference pathway for ground water flow ☐ Potential preferences pathway to ground water	
Surrounding Population	☐ Industrial ☐ Residential ☐ Shoreline ☐ Rural ☐ Unpopulated ☐ Others (specify).....	
Section 6 - Weather		
	Sea Conditions	☐ Calm ☐ Rough ☒ Not Applicable ☐ Low Tide ☐ High Tide
	Weather Conditions	☐ Bright Sunny ☐ Partly Cloudy ☐ Slight Rain ☒ Others (specify): Clear
	Temperature	
	Wind Direction	Northwest
	Wind Speed	
	Relative Humidity	

Section 7 – Receptor Assessment					
Sensitive Receptor	Pathway Impacted Area(m ²)	Distance To Impacted Area (m ²)	Estimated Area of Impact Area(m ²)	Receptor Impacted (Yes/No)	Remarks
Farmland					
Fish Pond					
Vegetation					
Surface Water					
Ground Water					
Venerable Object					
Human Habitation					
Wildlife					
Livestock					
Plantation					
Swamp					

GENERAL REMARK (to include visual observations on impacted area)

[GeneralRemarks]
.....
.....
.....

REPORTING OFFICER: Iyiola Olumide
DESIGNATION: General Manager, Offshore Terminal Operations

Initial


Signed by:


SIGNATURE: 83FDB9DCEAE7453... DATE:

*Clean-up program report must be submitted within 2 weeks of spill incidence.