

2026/LAR/013

0.00356/49



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: DAND

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 25/05/2026 ii. Date first reported: 26/05/2026
 iii. Date of first investigation: 26/05/2026
 iv. Date of follow-up investigation:
 v. Time investigation started: 1:35 p.m.
 vi. Estimated quantity spilled: 0.2 bbl

4. Site Details

- i. Site/Location: 4" OB, ATU 21L F/L
 ii. Position of Spill/Leak: N: 5° 23' 37.89" E: 6° 35' 52.85"
 iii. Spill area

- ☒ Land
 ☒ Swamp
 ☐ Freshwater
 ☐ Mangrove
 ☒ Coastline
☒ Near shore
☐ Offshore
☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom
☒ Trenches
☐ Bund Wall
☐ Sorbents
☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
☒ 10 O'Clock
☒ 2 O'Clock
☒ 3 O'Clock
☒ 4 O'Clock
☒ 5 O'Clock
☒ 6 O'Clock
5-7' clock ✓

ii. Type of Oil Contaminant

- ☒ Crude Oil
☒ Condensate
☒ Chemicals
☒ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline
☒ Flow Line
☒ Wellhead
☒ Manifold
☒ Flow Station
☒ Rig
☒ Storage Tank
☒ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion
☒ Equipment Failure
☒ Third Party Interference
☒ Accident
☐ Operational Error
☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
☒ Drilled Holes
☐ Blasting
☐ Theft
☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
Dead floating crabs Withering of vegetation Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. ORIHATU / OMOKU

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 6.000 m²

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/
/	/	/	/
/	/	/	/
/	/	/	/

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

Improve Surveillance of
affected Area and Clean up Impacted area
② Effect Immediate repair of the facility

12. Time Investigation ended..... 3pm

13. Name and Signature of Participants

❖ NOSDRA

1. Eziwe Stella Utunwa 26/5/2026 (Signature)

2.

3.

❖ NUPRC/NMDPRA

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. Kuru-Te, J-O (Signature) 26/05/2026

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1. JOHNSON Lucky BKS (Signature) 26/05/2026

2. CHARLES OMBURU 26/05/26

3. OZZO O. ISMA (Signature) 26/05/26

❖ COMMUNITY

1. Omokw

2. Okwudiri Ahali

3. Atakwu 26/5/26