

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☐ Mapping

9. Samples taken... NIL

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation NEPL Should ensure they carry out quarterly integrity test. They should clean up the environment and Remediate the soil also.

12. Time Investigation ended 14:50 HRS

13. Name and Signature of Participants