



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY  
JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters*

1. Company: NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify).....
3. Incident Details  
i. Date of Incident: 17/03/16    ii. Date first reported: 18/03/2016  
iii. Date of first investigation: 21/3/2016    iv. Spill Incidence No: 2016/LAR/028/084  
v. Date of follow-up investigation: 22/03/2016  
vi. Time investigation started: 14:30 HRS  
vii. Estimated quantity spilled(bbls): 3.4003786    viii. Quantity Recovered: NIL
4. Site Details  
i. Site/Location: TAYLOR CREEK 2S F/L AT ALUMONI  
ii. State: BAJELSA    iii. L.G.A: YANEGODA  
iv. Spill Co-ordinates: N(m) 05° 07' 36.7"    E(m) 5° 07' 36.7"  
v. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (specify).....  
vi. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund wall    ☒ Sorbents    ☒ Others (specify) NONE
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☐ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☒ 3 O' Clock  
☐ 4 O' Clock    ☒ 5 O' Clock    ☐ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (specify) .....
- iii. Facility  
☒ Pipeline    ☒ Flow line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant    ☒ Others (specify) .....
- iv. Cause Of Spill.  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (specify).....
- v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (specify).....



1. Properties impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water  
☒ Venerable Objects ☒ Others (specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes  
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift  
☒ Permanent ☒ Others .....

8. Extent of Impact

a) Community (indicate name)

- i. AKUMONI  
 ii. ....  
 iii. ....  
 iv. ....

b) Land (indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

b) Creeks/Creek lets

☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

c) Swamp

☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

d) River

☐ Tidal ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. Photograph/Map/Chart Rel.

☒ Still photographs ☒ Video coverage ☐ Mapping

10. Samples taken..... NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation AmcusaW out from 3 O'clock to 5 O'clock  
position WAS OBSERVED ON THE FACILITY. CLEAN-UP IS  
REQUIRED. INCREASE SECURITY IS REQUIRED IN THE AREA.

13. Time investigation ended .....