

PICTURES TAKEN ON SITE



Sign of bunkering activities



3" Nipple mounted on the pipeline by vandals



10" pipe still intact



Repaired.