



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 09./02./2016 ii. Date first reported: 09./02./2016
iii. Date of first investigation: 10./02/2016 iv. Spill Incidence No: 2016/SAR/035
v. Date of follow-up investigation:/...../.....
vi. Time investigation started: 1501 hrs
vii. Estimated quantity spilled(bbls): 32 bbls viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 6" LEVEL CONTROL VALVE (LCV) @ OBAMA F/S
ii. State: BAYELSA iii. L.G.A: NEMBE
iv. Spill Co-ordinates: N(m) 04° 21' 15.0"
E(m) 006 16' 09.4"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
vi. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
- iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
- iv. Cause Of Spill.
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
- v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) FAILED VALVE

i. **Properties impacted by the incident**

☒ Farmland ☒ Fish Pond ☐ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects ☒ Others (specify).....

ii. **Nature of impact**

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation..... Clean-up of inspected area and regular facility inspection required to prevent such from occurring.

13. Time investigation ended 1800 hrs.

14. Name and Signature of Participants