



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: SHELL PETROLEUM DEV. COMPANY LIMITED

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 18/02/2016 ii. Date first reported: 19/02/2016

iii. Date of first investigation: 21/04/2016 iv. Spill Incidence No.: 1577647

v. Date of follow-up investigation: 22/04/2016

vi. Time investigation started: 13:40 HRS, 9:22 HRS

vii. Estimated quantity spilled(bbls): 114 viii. Quantity Recovered: NIL

4. Site Details

i. Site/Location: 20° OF PULUWA / BRASS CREEK TANK LINE @ AMOGSE

ii. State: BAYELSA iii. L.G.A.: EKEREMOR

iv. Spill Co-ordinates: N(m) 04 56 31
E(m) 005 41 13.1 (0-149 Ha)

v. Spill area

☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify).....

vi. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) COFFEE DAM
EARTH DYKE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (specify)

iii. Facility

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)

iv. Cause Of Spill.

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify)

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

☐ Others (specify) UNKNOWN PERSONS INSTALLED A 4"

VALVE AT 12 O-CLOCK POSITION FOR OIL THEFT



20/1/15
J. J. J. J. J.
↓