



63

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:

☒ Oil Pollution
 ☐ Fire/Explosion
 ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....
3. Incident Details

i. Date of Incident: 12/03/2016
 iii. Date of first investigation: 15/03/2016
 v. Date of follow-up investigation:
 vii. Estimated quantity spilled(bbls): 0.13 BBLS

ii. Date first reported: 12/03/2016
 iv. Spill Incidence No.: 2016/SAR/052
 vi. Time investigation started: 13:00 HRS.
 viii. Quantity Recovered: NIL
4. Site Details

i. Site/Location: TEBIDABA FLOW STATION DELIVERY C
 ii. State: BAYELSA
 iv. Spill Co-ordinates: N(m) 04 33 24.6
 E(m) 005 55 09 -1

iii. L.G.A.: SOUTHERN LAW

v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....

vi. Structural Controls in Place
☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point

i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility
☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☒ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)

iv. Cause Of Spill.
☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) FAILURE OF CHECK VALVE

v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) None



64
1. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

i. OLUGBO Kingdom (OKORAMMA)

ii.

iii.

iv.

b) Land (indicate area in m²)

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation.....

CLEANUP OF IMPACTED SITE
SHOULD COMMENCE IMMEDIATELY. NAOC SHOULD
IMPROVE ON TIMELY CONDUCT OF JIV

13. Time investigation ended

14:20 HRS.