



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: **NIGERIAN AGIP OIL COMPANY (NAOC)**
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: **03/06/2016** ii. Date first reported: **03/06/2016**
 - iii. Date of first investigation: **05/06/2016** iv. Spill Incidence No. **2016/LAR/046**
 - v. Date of follow-up investigation:
 - vi. Time investigation started: **14:15 HRS**
 - vii. Estimated quantity spilled(bbls): **0.015** viii. Quantity Recovered: **NIL**
4. Site Details
 - i. Site/Location: **TAYLOR CREEK 2SS F/L @ IKARAMA**
 - ii. State: **BAYELSA** iii. L.G.A: **JENAGOA**
 - iv. Spill Co-ordinates: N(m) **05° 09' 55.4"**, **05° 09' 49.2"**
E(m) **006° 26' 27.3"**, **006° 26' 22.5"**
 - v. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
 - vi. Structural Controls in Place
☒ Boom ☐ Trenches ☒ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock **12-3 O'CLOCK ☒**
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock **12-2 O'CLOCK ☒**
 - ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
 - iii. Facility
☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....



i. **Properties impacted by the incident**

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. **Nature of impact**

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. **Delineation of impacted area**

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. **Extent of Impact**

a) **Community (indicate name)**

- i.
 ii.
 iii.
 iv.

b) **Land (indicate area in m²)** 2.2

- i.
 ii.
 iii.
 iv.

b) **Creeks/Creek lets**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... N/A.....

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation..... SURVEILLANCE OF THE
FACILITIES SHOULD BE INTENSIFIED.....

13. Time investigation ended 17:30 HRS.....