

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIA AGIP OIL COMPANY

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: 28/06/2016 ii. Date first reported: 28/06/2016

iii. Date of first investigation: 28/06/2016 iv. Spill Incidence No.: 2016/SAR/089

v. Date of follow-up investigation: 28/06/2016

vi. Time investigation started: 12:10pm

vii. Estimated quantity spilled(bbls):..... viii. Quantity Recovered: NIL

4. Site Details

i. Site/Location: 18" TEBIDABA/BRASS @ OYEREBENE -

ii. State: BAYELSA iii. L.G.A.: SOUTHERN IJAW

iv. Spill Co-ordinates: N(m) 04° 29' 43.1"
E(m) 006° 00' 42.0"

v. Spill area

☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify).....

vi. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (specify).....

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill.

☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☒ Accident

☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (specify)..... 3" valve installed

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
ii.
iii.
iv.

(b) Land (Indicate area in m²)

- i.
ii.
iii.
iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation. *NAOC should increase on surveillance to avoid further occurrence.*

12. Time Investigation ended. *4:30pm*