



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY  
JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters*

1. Company: **NIGERIA AGIP OIL COMPANY**
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☒ Fire/Explosion    ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify).....
3. Incident Details  
i. Date of Incident: **02.7.2016**    ii. Date first reported: **02.7.2016**  
iii. Date of first investigation: **2.7.2016**    iv. Spill Incidence No: **2016/NL/SAR/014**  
v. Date of follow-up investigation: **2.7.2016**  
vi. Time investigation started: **10:23am**  
vii. Estimated quantity spilled(bbls): **NIL**    viii. Quantity Recovered: **NIL**
4. Site Details  
i. Site/Location: **18" TEBIDABA - LAGOS GBENE**  
ii. State: **BAYELSA**    iii. L.G.A: **SOUTHERN - IJAW**  
iv. Spill Co-ordinates: N(m) **04° 28' 30.0"**  
E(m) **006° 07' 51.5"**  
v. Spill area  
☒ Land    ☒ Swamp    ☒ Freshwater    ☒ Mangrove    ☒ Coastline  
☒ Near shore    ☒ Offshore    ☒ Others (specify).....  
vi. Structural Controls in Place  
☒ Boom    ☒ Trenches    ☒ Bund wall    ☒ Sorbents    ☒ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock    ☒ 10 O' Clock    ☒ 2 O' Clock    ☒ 3 O' Clock  
☒ 4 O' Clock    ☒ 5 O' Clock    ☒ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil    ☒ Condensate    ☒ Chemicals    ☒ Refined Products  
☒ Others (specify).....  
iii. Facility  
☒ Pipeline    ☒ Flow line    ☒ Wellhead    ☒ Manifold    ☒ Flow Station    ☒ Rig  
☒ Storage Tank    ☒ Compressor Plant    ☒ Others (specify).....  
iv. Cause Of Spill.  
☒ Corrosion    ☒ Equipment Failure    ☒ Third Party Interference    ☒ Accident  
☒ Operational Error    ☒ Others (specify).....  
v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks    ☒ Drilled Holes    ☒ Blasting    ☒ Theft    ☒ Acid  
☒ Others (specify).....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
☐ Others (Specify) .....

### ii. Nature of impact

- ☐ Oil stained vegetation  
☐ Oil stained fishing nets  
☐ Dead floating fishes  
☒ Dead floating crabs  
☐ Withering of vegetation  
☐ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### (c) Creek/Creek lets

- ☐ Tidal  
☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

- ☐ Tidal  
☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

- ☐ Tidal  
☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

- ☐ Tidal  
☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

## 8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

## 9. Samples taken.....

## 10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

## 11. Remarks/Recommendation.....

4" valve was installed on the facility by unknown person(s) for oil theft activities.

## 12. Time Investigation ended.....

4:20 pm