

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: **NIGERIA AGIP OIL COMPANY (NAOC)**
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: **07/03/2016** ii. Date first reported: **07/03/2016**
iii. Date of first investigation: **07/03/2016** iv. Spill Incidence No: **2016/SAR/046**
v. Date of follow-up investigation: **07/03/2016**
vi. Time investigation started: **12:13 HRS**
vii. Estimated quantity spilled(bbls): **0.02 BBL** viii. Quantity Recovered: **NIL**
4. Site Details
i. Site/Location: **18" TEBIDABA / BRASS PIPELINE @ BENIKRUKRI**
ii. State: **BAYELSA** iii. L.G.A: **SOUTHERN IJAW L.G.A**
iv. Spill Co-ordinates: N(m) **N04° 32' 12.8"**
E(m) **E005° 58' 49.1"**
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☐ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause Of Spill.
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



1. **Properties impacted by the incident**

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. **Nature of impact**

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. **Delineation of impacted area**

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. **Extent of Impact**

a) **Community** (indicate name)

- i.
 ii.
 iii.
 iv.

b) **Land** (indicate area in m²)

- i.
 ii.
 iii.
 iv.

h) **Creeks/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Rel.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... NIL

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....

2" valve installed with 2" pipe
Connected on the facility @ 12 o'clock for oil
theft activities!

13. Time investigation ended

13:45 HRS