NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

☑ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) .....

3. Incident Details

i. Date of Incident: 15TH JULY 2016 ii. Date first reported: .....

iii. Date of first investigation: 21st July, 2016

iv. Date of follow-up investigation: .....

v. Time investigation started: 11:52 Am

vi. Estimated quantity spilled: 0.1bbl

4. Site Details — OBIGBO NORTH WELL 26T, 18S, 20T AND

i. Site/Location: — THREE (3) OTHER DISUSED FLOWLINES.

ii. Position of Spill/Leak: N04° 53' 34.3", E007° 07' 19.3"

iii. Spill area

☑ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify).....

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☑ 3 0'Clock

☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

☑ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) .....

iii. Facility

☐ Pipeline ☑ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☑ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☑ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify) .....

6. Impact of Incident

i. Properties Impacted by the incident

☐ Farmland ☐ Fish Pond ☑ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (Specify) .....

ii. Nature of impact

☑ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) .....

iii. Delineation of Impacted area

☑ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (*Indicate name*)

i. .....

ii. .....

iii. .....

iv. .....

(b) Land (*Indicate area in m^2*)

i. .....

ii. .....

iii. .....

iv. .....

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A		

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A		N/A	

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A	N/A	

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A	N/A	

8. Photograph/Map/Chart Ref.

☑ Still photographs ☑ Video coverage ☐ Mapping

9. Samples taken. N/A

10. Investigation carried out by

☑ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. SPDC should improved on their surveillance and also the clean up of the impacted area should be carry out as soon as possible

12. Time Investigation ended. 4:15 pm

13. Name and Signature of Participants