



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NOC)
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 19/01/16 ii. Date first reported: 19/01/16
 - iii. Date of first investigation: 19/01/16 iv. Spill Incidence No.: 2016/SAR/015
 - v. Date of follow-up investigation: -/-/-
 - vi. Time investigation started: 1000 HRS
 - vii. Estimated quantity spilled(bbls): 12 viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 18" ORAWA/BRASS P/L @ GOLUBOKIRI
 - ii. State: BAYELSA iii. L.G.A.: NEUBE
 - iv. Spill Co-ordinates: N(m) 04° 28'
E(m) 006° 15' 30.4"
 - v. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - vi. Structural Controls in Place
 - ☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☒ Others (specify) RISER
 - iv. Cause Of Spill.
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☐ Hacksaw Marks ☐ Drilled Holes ☒ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify).....



6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others **NONE**

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

10. **Samples taken**.....X1/A.....

11. **Investigation carried out by**

☐ Foot ☒ Boat ☐ Aircraft

12. **Remarks/Recommendation**

① A SECTION OF THE PIPELINE
RISER WAS IMPACTED BY A BLAST.
② CLEAN AND REMEDIATION IS REQUIRED.

13. **Time investigation ended**