

- i. Properties impacted by the incident
☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) ADJOINING WATER BODY
- ii. Nature of impact
☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....
- iii. Delineation of impacted area
☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW
7. Type of properties/ structures, if any, found outside the right-of-way
☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

- a) Community (indicate name)
i.
ii.
iii.
iv.
- b) Land (indicate area in m²) 1,032.027m²
i.
ii.
iii.
iv.

b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Rel.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... NIL

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation Immediate clean up is required.

✓ The Impacted area required remediation.

✓ Improve Surveillance and Security of Facility

13. Time investigation ended 1200 HRS