



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 20/06/2016 ii. Date first reported: 20/06/2016
 - iii. Date of first investigation: iv. Spill Incidence No: 2016/SAR/NL1011
 - v. Date of follow-up investigation:/...../.....
 - vi. Time investigation started:
 - vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 18" TEBIDABA/BRASS PIPE LINE AT OYEREGBENE
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN ITAKI
 - iv. Spill Co-ordinates: N(m) NO 30' 18.4"
E(m) EO 03' 22.5"
 - v. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - vi. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. Cause Of Spill.
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify).....



1. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... NIL

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... NIL

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others NIL

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
.....			
.....			
.....			

9. Photograph/Map/Chart Rel.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation..... the operator should improve
on her surveillance and security along its
pipeline to reduce sabotage incidents.

13. Time investigation ended 16:20 hrs