



# NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

## JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:  
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify).....
3. Incident Details  
i. Date of Incident: 03/09/2016 ii. Date first reported: 03/09/2016  
iii. Date of first investigation: 03/09/2016 iv. Spill Incidence No. 2016/NL/SAR/022  
v. Date of follow-up investigation: .....  
vi. Time investigation started: 10:53HRS  
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details  
i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT LAGOS GBENIE  
ii. State: BAYELSA iii. L.G.A: SILGA  
iv. Spill Co-ordinates: N(m) N04° 27' 52.8"  
E(m) E006° 09' 42.2"  
v. Spill area  
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline  
☒ Near shore ☒ Offshore ☐ Others (specify).....  
vi. Structural Controls in Place  
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock  
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock  
ii. Type of Oil contaminant  
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (specify).....  
iii. Facility  
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig  
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....  
iv. Cause Of Spill.  
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident  
☒ Operational Error ☒ Others (specify).....  
v. Visible Sign of Third Party Interference  
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid  
☐ Others (specify).....

## 6. Impact of Incident

### i. Properties impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
☒ Others (specify).....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
☒ Withering of vegetation  
☒ Others.....

### iii. Delineation of impacted area

- ☐ Within Company's facility/ROW  
☐ Outside Company's facility/ROW

## 7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops  
☐ Fish Farm/ Pond  
☐ Fishing net  
☐ Makeshift  
☐ Permanent  
☐ Others .....

## 8. Extent of Impact

### a) Community (indicate name)

i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### b) Land (indicate area in m<sup>2</sup>)

i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### h) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

9. **Photograph/Map/Chart Ref.**

☒ Still photographs    ☐ Video coverage    ☐ Mapping

10. **Samples taken**.....

11. **Investigation carried out by**

☐ Foot    ☒ Boat    ☐ Aircraft

12. **Remarks/Recommendation**.....

.....

.....

13. **Time investigation ended** .....