

PHOTOGRAPHS TAKEN ON SITE




FIG 1: Spill point with blast 6 O clock position and Hack saw cut at 10 O clock to 2 O clock position