

PHOTOGRAPHS TAKEN ON SITE




FIG 1-2: Spill point



FIG 3: Spill point after repairs



FIG 4: Impacted area