



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident:...../...../..... ii. Date first reported: 31/05/2016
iii. Date of first investigation: 02/06/2016 iv. Spill Incidence No. 2016/SAR/079
v. Date of follow-up investigation:...../...../.....
vi. Time investigation started: 13:35 HRS.
vii. Estimated quantity spilled(bbls): 15 BBLS viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: AZUZUAMA 1T WELLHEAD
ii. State: BATELSA iii. L.G.A.: SOUTHERN IJAW
iv. Spill Co-ordinates: N(m) 04° 42' 40.6"
E(m) 005° 55' 18.4"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock N/A
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause Of Spill.
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify) VANDALS REMOVED CCM OF WELLHEAD

- i. Properties impacted by the incident
 - ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
 - ☒ Venerable Objects ☒ Others (specify).....
- ii. Nature of impact
 - ☒ Oil stained vegetation ☐ Oil stained fishing nets ☒ Dead floating fishes
 - ☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....
- iii. Delineation of impacted area
 - ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW
7. Type of properties/ structures, if any, found outside the right-of-way
 - ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift
 - ☒ Permanent ☒ Others

(18,660.79m²)

8. Extent of Impact




a) Community (indicate name)

- i. AZUZUAMA
- ii.
- iii.
- iv.









b) Land (indicate area in m²)

- i.
- ii.
- iii.
- iv.





b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>AZUZUAMA</u>			
<u>RIVER</u>			







c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			
			

d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			
			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			
			

9. Photograph/Map/Chart Rel.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... NIL

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation..... WELL WAS STILL DRIPPING
AS AT TIME OF JIV, THERE WAS NO AGREEMENT
ON DATE OF INCIDENT. CLEANUP MUST COMMENCE IMMEDIATELY

13. Time investigation ended 15:17 HRS