



2016/LAR/091/223

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify) GASEOUS EMISSION

3. Incident Details

i. Date of Incident: 14th SEPT 2016 ii. Date first reported: 14th SEPT 2016

iii. Date of first investigation: 15th SEPT 2016

iv. Date of follow-up investigation: N/A

v. Time investigation started: 1400HRS

vi. Estimated quantity spilled: N/A

4. Site Details

i. Site/Location: 4" DSH IE ISS FLOWLINE CLOSE TO THE LOCATION DSH IE

ii. Position of Spill/Leak: N05° 05' 43.2", E006° 27' 37.6"

iii. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify).....

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☒ Others (Specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock

☒ 4 0'Clock ☐ 5 0'Clock ☒ 6 0'Clock

ii. Type of Oil Contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) N/A

iii. Facility

☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify).....

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify).....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *N/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *N/A*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii. *N/A*
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii. *N/A*
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....
SURVEILLANCE SHOULD BE IMPROVED
TO AVOID ANOTHER VANDALIZATION
.....
.....

12. Time Investigation ended.....