



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 14/3/2016 ii. Date first reported: 16/03/16
iii. Date of first investigation: 17/3/2016 iv. Spill Incidence No.: 1595524
v. Date of follow-up investigation: /
vi. Time investigation started: 13:41pm
vii. Estimated quantity spilled(bbls): 72bbls viii. Quantity Recovered: NIL

4. Site Details

- i. Site/Location: ETELEBOU FLOW STATION
ii. State: BAYELSA iii. L.G.A.: YENAGOA
iv. Spill Co-ordinates: N(m) 05° 01' 29.9"
E(m) 06° 21' 38.3"

v. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....

vi. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☒ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)

iv. Cause Of Spill.

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☒ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify)..... NON



1. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)930 m²

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Rel.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... *NON*

11. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation..... *THE IMPACTED AREA SHOULD
BE CLEANED UP IMMEDIATELY.*

13. Time investigation ended *15:30 pm*