



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify): OIL THEFT POINT
3. Incident Details
i. Date of Incident: 17/09/2016 ii. Date first reported: 17/09/2016
iii. Date of first investigation: 17/09/2016 iv. Spill Incidence No. 2016/SAR/NL/026
v. Date of follow-up investigation: NIL
vi. Time investigation started: 11:07 AM
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 18" TEB/DABA/BRASS PIPELINE AT LAFSIBENE
ii. State: BAYELSA iii. L.G.A.: SOUTHERN IYEM
iv. Spill Co-ordinates: N(m) N 04° 28' 29.8"
E(m) E 006° 07' 11.9"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify):
vi. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify):
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify): THEFT POINT
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify):
iv. Cause Of Spill.
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify):
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify):

i. Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift
☒ Permanent ☒ Others VEGETATION

8. Extent of Impact

a) Community (indicate name)

i.
 ii. NIL
 iii.
 iv.

b) Land (indicate area in m²)

i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... NO

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation..... SECURITY SURVEILLANCE
SHOULD BE INTENSIFIED AROUND THE
FACILITY.

13. Time investigation ended 2:10 PM