

PICTURES TAKEN ON SITE(Appendix 2)



4" Valve connected to 3" pipe installed by vandals for the purpose of oil theft.



Repaired point.