

PHOTOGRAPHS TAKEN ON SITE



FIG 1: Spill point on arrival at site



FIG 2: Spill point on excavation



FIG 3: Pegging of spill point



Repair of spill point (coning)