



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) water

3. Incident Details

- i. Date of Incident: 11/3/2016 ii. Date first reported: 27/4/2016
iii. Date of first investigation:
iv. Date of follow-up investigation: 15/11/16
v. Time investigation started: 1353hrs
vi. Estimated quantity spilled: —

4. Site Details

- i. Site/Location: 24" BONNY-BONNY PIPELINE (OPOBO CHANNEL)
ii. Position of Spill/Leak: N 04° 32' 25.9" E 007° 40' 48.3"
iii. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) coggerdam

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☒ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify) fresh water

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☐ Others (Specify) *oil*

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☐ Others (Specify) *oil*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW
☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. *owokiri*

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation. SPDC should routinely check
their facilities and possibly make replacements
where necessary

12. Time Investigation ended.....